

Technical Information

2/2004

911 GT3 Cup and 911 GT3 RS

Adapter Set for Recaro Seat

Vehicles concerned: 911 GT3 Cup, 911 GT3 RS

Part Number: 996.521.923.91

Part: Adapter set (in spare parts catalogue listed as angle plate)

Damage cause: manufacture based crack formation in the bending radius

Date of effectiveness: Model Year 2002

On the angle plate of the adapter set for the Recaro seat, cracks have been detected within the bending radius of the 90 degree angle. This damage case occurred on a 911 GT3 Cup car which was delivered in 2002. The cracks are due to faulty manufacturing when reshaping the part.

For this reason, you are requested to check the adapters mounted in your 2002 MY car. If the adapters have any damages similar to those as shown on the attached photo, we would ask you kindly to return the faulty part(s) to Porsche AG. A replacement will be sent to you free of charge as soon as we have received the damaged items. In order to facilitate the handling procedure, please note the following:

1. Shipping address:

Dr.Ing.h.c.F. Porsche AG

Att.: Marcus Stolzenthaler

Product Management Motorsport Cars

Porschestrasse

71287 Weissach, Germany

Tel. +49-7 11-9 11-24 98

2. The following information must be included in the shipment:

=> Your address and the name of the person to contact as well as the shipping address (if this is different from your address).

=> Chassis Number of your vehicle

Porsche Motorsport
April 2004

**Attachment to
Technical Information
2/2004**

**911 GT3 Cup and 911 GT3 RS
Adapter Set for Recaro Seat**

*Adapter
Porsche Part Number 996.521.923.91*



Cracks in the bending radius (see white markings)

